SF000/B firmware revision history

Firmware version	Change log	Description	Hardware revision	Release date
1.4.0	Changed: • Change to Hardware Rev10 to indicate the use of the IR Black lenses	New Hardware revision	10	05/11/2026
1.4.0	Changed: • Change to Hardware Rev9. Board design update due to component shortages. Added: • Signal encoding to minimise cross talk between sensors	New Hardware revision/Added features	9	20/10/2026
1.3.3	Changed: • Change to Hardware Rev8 for wider temperature performance Firmware update for improved temperature distance compensation	New Hardware revision / Improvement	8	30/04/2026
1.3.1	Changed: Change the Hardware Rev to 7.1 (71)	New Hardware revision	7.1 (71)	08/10/2025
1.3.1	Fixed: • I2C communication fix for Pixhawk	Bug Fix	7	29/02/2024
1.3.0	Initial release for new Hardware Rev7	New Hardware revision	7	05/05/2023
1.2.1	Changed: • Changed default state of LED to Off	Setting Change	3,4	12/05/2023
1.2.0	Added filters: (configurable) • Smoothing • Rolling average • Median Added: • I2C bus speed selection • Brownout detection	Improvement/ features added	3,4	04/11/2021

1.1.0	• I2C lines are now in the correct position	Major	3,4	03/09/2020
1.0.2	• Initial release	Initial release	3	03/08/2020