

SF000/B firmware revision history

Firmware version	Change log	Description	Hardware revision	Release date
1.3.3	Changed: <ul style="list-style-type: none"> Change to Hardware Rev8 for wider temperature performance Firmware update for improved temperature distance compensation 	New Hardware revision / Improvement	8	30/04/2026
1.3.1	Changed: Change the Hardware Rev to 7.1 (71)	New Hardware revision	7.1 (71)	08/10/2025
1.3.1	Fixed: <ul style="list-style-type: none"> I2C communication fix for Pixhawk 	Bug Fix	7	29/02/2024
1.3.0	Initial release for new Hardware Rev7	New Hardware revision	7	05/05/2023
1.2.1	Changed: <ul style="list-style-type: none"> Changed default state of LED to Off 	Setting Change	3,4	12/05/2023
1.2.0	Added filters: (configurable) <ul style="list-style-type: none"> Smoothing Rolling average Median Added: <ul style="list-style-type: none"> I2C bus speed selection Brownout detection 	Improvement/features added	3,4	04/11/2021
1.1.0	<ul style="list-style-type: none"> I2C lines are now in the correct position 	Major	3,4	03/09/2020
1.0.2	<ul style="list-style-type: none"> Initial release 	Initial release	3	03/08/2020

