

SF20HA & LW20HA firmware revision history

Firmware version	Change log	Description	Hardware revision	Release date
4.4.6	Changed: <ul style="list-style-type: none">New hardware revision Rev20Improved calibration for short range performance Fixed: <ul style="list-style-type: none">Fixed false alarm triggers generated on lost signals	New Hardware Rev/ Bug fix	20	23/04/2026
4.4.5	Fixed: <ul style="list-style-type: none">Fixed I2C receive buffer length to allow messages longer than 16bytes Changed: <ul style="list-style-type: none">Improved temperature compensation for High Accuracy Calibration	Bug Fix/ Improvements	19.1	17/07/2025
4.4.3	Initial Release for SF20HA and LW20HA	Initial Release	19.1	17/03/2025

